THE KLEAN SCREEN™ LINE-UP

PATENT PENDING



#2-1357 • TOMCO'S MOST POPULAR!

Applications: Buick, Cadillac, Chevrolet, Chevrolet Truck, GMC Truck, Oldsmobile, Oldsmobile Truck, Pontiac, Pontiac Truck, Saturn 1992-2002 🖈

ASSOCIATED TECHNICAL SERVICE BULLETIN: GM 96097

ASSOCIATED MIL CODES: 32, P0401, P1406



#2-1379 • Fits 3.8L GM Linear EGR Valves.

Applications: Buick, Chevrolet, Chevrolet Truck, Oldsmobile, Oldsmobile Truck, Pontiac, Pontiac Truck 1994-2003 *

ASSOCIATED MIL CODES: P0401, P1406





Ford Sonic Part# 2-1121

#2-1121 • The ORIGINAL KLEAN SCREEN™!

Applications: Ford, Ford Truck, Lincoln, Mercury 1980-1993 ★

ASSOCIATED MIL CODES: 31, 32, 33




Ford PFE/DPFE with Basket Part# 2-1377

#2-1377 • Includes a KLEAN SCREEN™ BASKET. The BASKET is placed in the tube before the EGR Valve. When used in conjunction with the gasket, gives DOUBLE protection to the passages!

Applications: Ford, Ford Truck, Lincoln, Mazda Truck, Mercury, Mercury Truck

1984-1997 *

ASSOCIATED MIL CODE: 332





Ford PFE/DPFE Part# 2-1378

#2-1378 • When passages need to be completely cleaned out to restore the EGR system to normal operation, this kit is the same as the #2-1377 but includes the replacement gasket for the intake adapter.

Applications: Ford, Lincoln, Mercury 1991-2002 ★

ASSOCIATED TECHNICAL BULLETIN: FORD 96-23-4 ASSOCIATED MIL CODES: 332, P1407, P1408





Ford Sonic with Basket Part# 2-1371

#2-1371 • Fits Ford Sonic Valves with "Screw On" Exhaust Tubes. Includes KLEAN SCREEN™ BASKET.

Applications: Ford, Ford Truck, Mazda Truck, Mercury 1984-1997

ASSOCIATED MIL CODES: 31, 32, 33, 332





Chrysler Part# 2-1370

#2-1370 • Chrysler EGR KLEAN SCREEN™

Applications: Chrysler, Chrysler Truck, Dodge Truck, Eagle, Plymouth, Plymouth Truck 1988-1997 🖈

ASSOCIATED MIL CODE: P0401



6241 Lemay Ferry Rd. St. Louis, MO 63129 Phone: 800-325-9972 Fax: 314-815-0027






KLEAN SCREEN™

EGR Valve Gaskets with Integrated Carbon Filters

"Catch carbon particles *before* they can cause trouble!"

PROBLEM: Every technician has experienced the frustrating situation with EGR Valves that are prone to carbon clogging. This carbon buildup can cause the EGR pintle to stick open or closed. The result can be rough idling, stalling, hesitations, surging, pinging, malfunction indicator lamps (MIL) to be set and or failed emissions tests. Even a new EGR Valve may very well foul again in a very short period of time.

SOLUTION: TOMCO, Inc. has developed **KLEAN SCREEN**™ **TECHNOLOGY** that actually **prevents** EGR Valves from fouling. The KLEAN SCREEN™ GASKET takes the place of the original equipment type gasket. The integrated carbon filter screen covers the hole where the exhaust gas enters. These heat resistant, stainless steel screens catch the carbon particles before they can cause trouble inside the EGR Valve. As heat is built up around the screen, these larger particles are burnt off or dissipated into smaller, non-clogging particles.



BENEFITS FOR THE TECHNICIAN

- ★ Corrects & Repairs an Original Equipment problem.
- * Reduces Comebacks.
- ★ Simple to Install Preventative Maintenance.
- ★ Doesn't just replace the part actually fixes a system problem.
- ★ Builds Credibility with **YOUR** Customer.
- **★ CUSTOMERSATISFACTION!**

BENEFITS FOR THE CONSUMER

- ★ Saves Costly EGR Valve Replacement of \$100 to \$500 or More!
- ★ Ends the Frustration of Continued EGR Valve Malfuntion.
- ★ Confidence in their **TECHNICIAN**.
- ★ Helps avoid the "Stranded Motorist".
- **★ CUSTOMERSATISFACTION!**

